



中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

维修许可证

MAINTENANCE ORGANIZATION CERTIFICATE

编号/No. F00100709

单位名称/NAME OF ORGANIZATION:

BP Aero Services, LLC

单位地址/BUSINESS ADDRESS:

4965 Hanson Drive Irving Texas 75038 USA

经审查，该单位符合中国民用航空规章第 145 部的要求，可以从事如下类别的维修工作：
Upon finding that the organization complies with the requirements of **CHINA CIVIL AVIATION REGULATION(CCAR)** Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

Component Maintenance

- ☆ -

本许可证除被放弃、暂停或吊销，在下述期限内将一直有效。

This certificate, unless cancelled, suspended, or revoked, shall continue in effect until:

2020-12-31

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2016-02-19

再次颁发日期/DATE REISSUED:

2018-12-20





中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目 LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F00100709 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F00100709
is/are limited to the following:

LOCATION: Irving Texas

Inspection, Repair, Overhaul and Modification of the following Components:

Powerplant (ATA-71): Limit to Powerplant System; Engine Mount Section; Powerplant System Wiring.

Turbine/turboprop Engine (ATA-72): Limit to Engine (Turbine/Turboprop); Turbine Engine Reduction Gear; Turbine Engine Air Inlet Section; Turbine Engine Compressor Section; Turbine Engine Combustion Section; Turbine Section; Turbine Engine Accessory Drive; Turbine Engine Oil System.

Air (ATA-75): Limit to Compressor Bleed Governor; Compressor Bleed Valve; Bleed Air Indicating System.

(To Be Continued)

- ☆ -

This approval will be in effect only on condition of local authority approval kept in valid.
All work should be accomplished in accordance with current manufacturer's manual and/or CAAC approved data.

局长授权/For the Administrator of CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2016-02-19

再次颁发日期/DATE REISSUED:

2018-12-20





中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目 LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F00100709 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F00100709
is/are limited to the following:

LOCATION: Irving Texas

Inspection, Repair, Overhaul and Modification of the following Components:

Engine Indicating (ATA-77): Limit to Engine Pressure Ratio (EPR); Engine BMEP/Torque Indicating; Engine Temperature Indicating System; Cylinder Head Temperature (CHT) Indicating System; Engine EGT/TIT Indicating System; Engine Ignition Analyzer System; Engine Ignition Analyzer; Engine Vibration Analyzer.

Engine Exhaust (ATA-78): Limit to Engine Collector/Tailpipe/Nozzle; Engine Thrust Reverser.

Starting (ATA-80): Limit to Engine Starter.

Detail as listed in CAAC approved maintenance capability list.

- ☆ -

This approval will be in effect only on condition of local authority approval kept in valid.
All work should be accomplished in accordance with current manufacturer's manual and/or CAAC approved data.

局长授权/For the Administrator of CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2016-02-19

再次颁发日期/DATE REISSUED:

2018-12-20

